
Blacksmith' s Shop and Cottage



Blacksmith' s Shop and
Cottage



Blacksmith' s Shop and
Cottage

Location

100 - 102 Main Street BACCHUS MARSH, MOORABOOL SHIRE

Municipality

MOORABOOL SHIRE

Level of significance

Included in Heritage Overlay

Victorian Heritage Register (VHR) Number

H0462

Heritage Overlay Numbers

HO8

Heritage Listing

Moorabool Shire

Statement of Significance

Last updated on - June 1, 1995

A small brick and stone blacksmith's shop built on the road to the Ballarat goldfields, in 1877 on the site where there had been a blacksmith's business since 1850 until 1961. The forge and chimney survive, but no equipment.

It is now a "bookbarn".

Adjoining this, is an early brick and stone cottage built in 1850, used as a residence by a succession of blacksmiths until 1961, now a museum. Pre-gold-rush buildings are very rare in Victoria.

The cottage is of state architectural significance as a rare, relatively intact survival of a pre-gold rush building, and on the route to the goldfields. The complex is also of significance as a representative embodiment of the way of life on the route to the gold fields at the time of the gold rush at Ballarat; and the blacksmiths as evidence of an industrial process of the 1870s and on a site where it had continued since 1850. It is associated with the development of relevant industry in the community life on this route. The cottage is a pioneering early building in Bacchus Marsh.

The complex is also of state historical significance in demonstrating the effect of a social movement (the gold rush).

The Blacksmith's Shop is also of social significance as known and valued by the community as part of its sense of identity of the place and as the embodiment of a sequence of varied approaches to conservation action, over twenty-five years.

Heritage Study/Consultant	Moorabool - Bacchus Marsh Heritage Study 1995, Richard Peterson and Daniel Catrice, 1995;
Other Names	Charles Edwards Blacksmith & Wheelwright,
Hermes Number	117617
Property Number	

Physical Conditions

Blacksmith. Reasonable. A downpipe in the south-west corner (not on the site) is not connected to the roof gutter. Brickwork is eroding. Repairs are in Portland cement, instead of lime mortar. Rising damp is occurring in the south-west corner (caused by the unconnected downpipe).

Cottage. Reasonable. There are structural cracks each side of the chimney as it meets the wall. Road and garden level have risen to be too high around the building, allowing damp to penetrate. It has been recently re-rendered.

Intactness

Blacksmith. Good. There are security grilles fixed to windows in front. There is some remnant roofing and roof plumbing. The old door is now obscured by inappropriate modern doors. It is not known if the original survives behind. The 12-paned window has been barred.

Cottage. Reasonable. Door, fence (except one surviving old post), render (?chimney has old render), roofing and roofplumbing are recent. There are historicist. The porch and fence appear to be an historicist re-creation. The sign is intrusive and inappropriate.

SIGNIFICANT INTACT ELEMENTS

MATERIALS. FORM. FACADE.

WALL DECORATION. DOORS. WINDOWS.

UNPAINTED FINISH.

Physical Description 1

Blacksmith's Shop. A small masonry mid-nineteenth century industrial building. Its gable roof faces Main Street fronted with a parapet on the boundary line to the street and to the adjoining property line at left, onto which three windows now directly face. There are three chimneys, one L-shaped! The parapet has deeply recessed panels. Windows and doors are segmental headed and windows have 12-pane double-hung sashes. The street door is of the split, stable type with a fanlight over. The front is rendered with a very sandy mix over random rubble honey coloured stone and the base is ashlar. The brickwork on the right hand side has been cement washed. The interior was not inspected. There are timber gabled buildings at the rear.

The large split stable door indicates the nature of the farrier work undertaken in the shop, through the form of the doors, the eroded threshold and brand marks tested on the timberwork. The building contains no equipment but the forge and chimney are intact in one corner. There are remnants of painted signage on the east wall, two apparently relating to forges and the third for a conventional fireplace. Behind the smithy is an open sided shed with lean to verandah, and gable roof cart shed or stable.

Cottage A hip-roofed double-fronted symmetrical masonry cottage. It physically abuts the blacksmith but does not share a wall with it. It is rendered random rubble construction in a honey-coloured stone. There is an internal chimney with old render and a timber gable roofed entrance porch. Quoins are formed in render at corners and windows have architraves and 12-pane double-hung sashes. There is a timber extension at the rear and a picket fence.

The cottage is described in 1852 as constructed of stone, however, the rear timber section which abuts the stone section has remaining posts suggesting that the stone wall was built. The structure of the rear timber rooms and verandah is interesting in several aspects: the morticed heads to the doors (suggesting construction prior to the establishment of the blacksmith's shop where nails are common), the lack of a ceiling (although in 1975 the calico lining was still in place), partial lining to interior walls, and beaded profile weatherboards.

Usage/Former Usage

USE: Book barn & Museum

PREVIOUS USE: Blacksmith & cottage

Historical Australian Themes

Township /Transport.Conservation.

This place/object may be included in the Victorian Heritage Register pursuant to the Heritage Act 2017. Check the Victorian Heritage Database, selecting 'Heritage Victoria' as the place source.

For further details about Heritage Overlay places, contact the relevant local council or go to Planning Schemes Online <http://planningschemes.dpcd.vic.gov.au/>