# Former Ranger Barracks (Duplicate)



Drill Hall Curtis St - Ballarat Heritage Review, 1998

#### Location

61 CURTIS STREET, BALLARAT CENTRAL, BALLARAT CITY

## Municipality

**BALLARAT CITY** 

# Level of significance

Included in Heritage Overlay

## Victorian Heritage Register (VHR) Number

H1949

## **Heritage Overlay Numbers**

HO23

# **Heritage Listing**

**Ballarat City** 

# **Statement of Significance**

Last updated on - April 15, 2024

What is significant? How is it significant? Why is it significant? Included on the Victorian Heritage Register (H1949).

#### Ballarat Conservation Study, 1978

No SoS provided in this citation. Please refer to descriptions, history, construction, loc govt, listings and images sections in this place record for further information.

#### Ballarat Heritage Review, 1998

No SoS provided in this citation. Please refer to history and images sections in this place record for more information.

Heritage Ballarat - Ballarat Conservation Study, Jacobs Lewis Vines Architects, 1978; Ballarat

Study/Consultant - Ballarat Heritage Review, Andrew Ward, 1998;

Construction dates 1885, 1924, 1927, 1913, 1937, 1939,

Architect/Designer Brittingham, Samuel C, Public Works Department,

Other Names Former Drill Hall,

Hermes Number 120444

**Property Number** 

## **Physical Description 1**

This hall was constructed in 1885 for the Department of Defence to a Public Works Department design. The drawing was signed by S.C. Brittingham, (then Assistant Architect (2nd grade) to the North Western District) and the constructor was James Taylor.

The building is a large ornate example of a timber army barracks building an is typical of the many army buildings constructed at this time. The 75 foot span of the main room is of note.

Externally the main facade of the building is substantially intact. The broad hood moulds and triangular window heads are of interest. Internally the original timber trusses shown on the original drawings have been replaced by metal trusses (of an early date) with curved edged connector plates. The internal doors are intact. The building to the left was built at the same time, but has lost the cast iron brackets to the posts, and the gable decoration and finial have been removed.

#### Integrity

#### SUBSTANTIALLY INTACT

This place/object may be included in the Victorian Heritage Register pursuant to the Heritage Act 2017. Check the Victorian Heritage Database, selecting 'Heritage Victoria' as the place source.

For further details about Heritage Overlay places, contact the relevant local council or go to Planning Schemes Online http://planningschemes.dpcd.vic.gov.au/