

# Victorian Heritage Database Report

Report generated 24/02/20



## COLONIAL BANK (FORMER)



23290 Colonial Bank Former Branxholme 0477 23290 Colonial Bank Former Branxholme 0478

---

### Location

Lynch Street BRANXHOLME, Southern Grampians Shire

### Municipality

SOUTHERN GRAMPIANS SHIRE

### Level of significance

Stage 2 study complete

### Heritage Listing

Southern Grampians Shire

---

### Statement of Significance

Last updated on - December 11, 2003

What is significant?

The former Colonial Bank is a single storey, symmetrical brick building of traditional house form located on the south side of Lynch Street near the intersection of Monroe Street. It had a timber and cast iron verandah across the western or garden elevation, which has collapsed. It is not certain when this building was constructed but, from its form, plan and detailing it does seem to have been built as a house rather than as a bank, and before 1870. No architect or builder has been associated with the design. The building has a low degree of integrity and is in poor condition.

How is it significant?

The former Colonial Bank is of historical and architectural significance to the community of Branxholme and to the Southern Grampians Shire

apparently the only bank in Branxholme. The former Colonial Bank is of architectural significance as an example of domestic architecture, particularly for the unusual side verandah.

Heritage Study/Consultant	Southern Grampians - Southern Grampians Shire Heritage Study, Timothy Hubbard P/L, Annabel Neylon, 2002;
Construction dates	1876,
Heritage Act Categories	Registered place,
Hermes Number	23290
Property Number	

---

## Physical Conditions

The building is in poor condition

## Physical Description 1

A single storey, symmetrical brick building of traditional house form, now painted, which formerly had a timber and cast iron verandah across the western or garden elevation. The northern half of the verandah was enclosed with weatherboards to dado height and sliding glazed sashes above. The roof is hipped with an M-shaped profile and is covered in corrugated iron. The front windows are 2-paned double hung sashes, while the side and rear windows are 12-paned double hung sashes. The two chimneys are located opposite the front windows. The rear half of the house (or its extension) is in weatherboard with the roof continued in the same materials, form and pitch.

## Historical Australian Themes

Theme 3 Developing local, regional and national economies

3.18 Financing Australia

3.18.2 Banking and lending

Theme 8 Developing Australia's cultural life

8.12 Living in and around Australian homes

8.14 Living in the country and rural communities

## Usage/Former Usage

vacant

## Integrity

low degree of integrity

*This place/object may be included in the Victorian Heritage Register pursuant to the Heritage Act 2017. Check the Victorian Heritage Database, selecting 'Heritage Victoria' as the place data owner.*

*For further details about Heritage Overlay places, contact the relevant local council or go to Planning Schemes Online <http://planningschemes.dpcd.vic.gov.au/>*