## **Victorian Heritage Database Report**

Report generated on - 02/08/24

## **RIDGE PARK**



S576 RidgePark BewareReefCapeConran HistoricView



S576 RidgePark BewareReefCapeConran DrawingOfWreck



S576 RidgePark BewareReefCapeConran Artefact

### Location

Beware Reef, Cape Conran

## Victorian Heritage Register (VHR) Number

S576

#### **Date lost**

10/02/1881

#### Official number

79304

#### **Construction material**

Iron

#### Hull

Iron screw steamer. 4 cemented bulkheads. Iron decked. Raised quarter deck 78ft. Bridge Deck 40ft. Fore Deck 20ft. Double bottom aft 73ft, double bottom fore 102ft. Foreward and aft peak tanks. Anchors and chains proofed.

## **Propulsion**

Steam - Screw

# Length/Breadth/Depth 214.00 Feet / 31.00 Feet / 15.50 Feet **Builder** S. P. Austin & amp; Co Year of construction 1878 **Built port** Sunderland **Built country** England **Registration Port** Adelaide **Date lost** 10/02/1881 **Departure** Adelaide **Destination** Sydney Cargo Brandy, wine, flour **Owner** Henry Simpson and Sons (Black Diamond Line) 1880

## Master

Captain Heslop

#### **Cause of loss**

Inattentive navigation

## **VHR** history

The SS Ridge Park was used as a collier by the Black Diamond Line of Adelaide. It also carried a limited number of passengers and general cargo on outward voyages from Adelaide to Newcastle. The vessel usually returned with a cargo of coal and some passengers from Sydney to Adelaide via Launceston. At 3.50am on 10 February 1881 the Ridge Park was carrying a cargo of brandy, wine and flour from Adelaide to Sydney when it struck the north western side of Beware Reef. The captain and crew took to the lifeboat and made for Gabo Island, which they reached the following day. They were later rescued by the SS Wentworth and taken to Sydney. The Ridge Park remained on the rocks for just over a month until a series of severe southerly gales washed the wreck into deeper water. Most of the cargo was salvaged. A Marine Board of Inquiry found that Captain Heslop and Chief Officer Peake had been inattentive to their duties while navigating close to the coast. Despite submitting letters in their defence both had their certificates suspended for three months.<br/>
| S Ridge Park include the straight stemmed triangular bow structure, winch, a squashed boiler, the engine, propeller and broken up hull plating in 7 - 24 metres depth on the north-western side of Beware Reef.<br/>
| S Ridge Park include the straight stemmed triangular bow structure, winch, a squashed boiler, the engine, propeller and broken up hull plating in 7 - 24 metres depth on the north-western side of Beware Reef.<br/>
| S Ridge Park include the Straight stemmed triangular bow structure, winch, a squashed boiler, the engine, propeller and broken up hull plating in 7 - 24 metres depth on the north-western side of Beware Reef.<br/>
| S Ridge Park include the Straight stemmed triangular bow structure, winch is salvage activities on the Ridge Park.