
Wyreena



Hull Rd 13

Location

13-23 Hull Road CROYDON, MAROONDAH CITY

Municipality

MAROONDAH CITY

Level of significance

Included in Heritage Overlay

Heritage Overlay Numbers

HO30

Heritage Listing

Maroondah City

Statement of Significance

Last updated on -

Wyreena Community Arts Centre (formerly Hayward), is a substantial double-storey Bungalow style house built in c1923, designed by Philip B. Hudson architect. It is historically significant as a representative embodiment of the comfortable way of life in the inter-war period, of an executive and his family in a rural setting. It is architecturally significant as representative of the domestic work of Hudson prior to his involvement with the design of the Shrine of Remembrance (1927-34). It is also architecturally significant as a representative of the two-storey Bungalow type influenced by the Vernacular Revival and the Chicago School. It later acquired social significance as a community focus.

Heritage Study/Consultant	Maroondah - Maroondah Heritage Identification Study, Richard Peterson with Peter Barrett, 1998;
Hermes Number	146902
Property Number	

Physical Description 1

Now with Silver Birches, set in pleasant and spacious mature parkland. A substantial double-storey clinker-brick bungalow, with a major gable facing Mount Dandenong Road. It is roughcast over doorhead height. Windows with unusual tripartite glazing bars, are expressed double-hung on corbels (now roughcast over). Upper gables have shingles and jetty. Rafters are exposed. Gable ends have deep eaves, supported on plain props to exposed purlins, with diamond ends. At front is a hipped pair of rectangular bays. At right projects a first floor balcony solarium (now infilled), with the entrance under, in the angle. This gable is more elaborate, with a decorative shallow eyebrow (cyma recta) hood, on bull-nosed brackets. The shingled cladding is concave over bull-nosed brackets. All is supported on four clinker piers. There are various mature pines in the grounds.

Intactness

The fence and hedge are recent. Roof tiles have been replaced with cement, now in poor condition. The roughcast has been re-applied more extensively and painted. The first floor verandah has been infilled with glazing. There have been various additions, particularly classrooms in the grounds

This place/object may be included in the Victorian Heritage Register pursuant to the Heritage Act 2017. Check the Victorian Heritage Database, selecting 'Heritage Victoria' as the place source.

For further details about Heritage Overlay places, contact the relevant local council or go to Planning Schemes Online <http://planningschemes.dpcd.vic.gov.au/>