Victorian Heritage Database Report

Report generated on - 12/10/24

SS CHEVIOT



S113 Cheviot HistoricView dateunknown



S113 Cheviot PortPhillipHeadsCheviotBeach PortPhillipHeadsCheviotBeach PortPhillipHeadsCheviotBeach Engine Feb1997



S113 Cheviot SideView Feb1997



S113 Cheviot SteamDeckEngine Feb1997



S113 Cheviot PortPhillipHeadsCheviotBeach PortPhillipHeadsCheviotBeach wreck Feb1997

Location

Cheviot Beach, Point Nepean

Victorian Heritage Register (VHR) Number

S113

Date lost

20/10/1887

Official number

63648

Hull

Number of masts
2
Length/Breadth/Depth
230.20 Feet / 32.20 Feet / 17.50 Feet
Builder
C. Mitchell & Co
Year of construction
1870
Built port
Low Walker, Newcastle
Built country
England
Registration Number
No. 39 of 1876
Registration Port
Melbourne
Date lost
20/10/1887
Departure
Melbourne
Destination
Sydney
Cargo
Metals, wine, foodstuffs, sundries, valued at 8000 pounds

Schooner-rigged; elliptical stern; clincher built; 1deck; 4 bulkheads 4; double-bottomed after and under 5engine

room

Propulsion

Steam - Screw

Owner

W. Howard Smith & Dry Sons Ltd

Master

Capt. Thomas B. Richardson

Weather conditions

Night; SW gale

Cause of loss

Drifted ashore after propellor fell off or blade hit floating wreckage

Passenger comments

There may have been an extra two passengers who boarded at the last minute, so the passenger numbers may be 33-35, and consequently the death toll may be 35-37 lives lost.

Number of crew

36

Statement of significance

The Cheviot is historically significant as a typical example of a coastal trading passenger and cargo steamship. It has the tragic distinction of being one of Victoria's worst shipwrecks with 35 lives lost, and is the worst shipwreck to have occurred at Port Phillip Heads in terms of loss of life.

VHR history

Loss of propeller while on outer edge of Rip made the vessel unmanageable. Sails were set immediately but it drifted ashore about 9 pm. Broke in two before going to pieces. Queenscliff lifeboat unable to get out through Heads, due to the appalling weather. A rocket life-line and boatswain's chair were the means by which 24 passengers and crew were saved. Some victims drowned, trapped in the fore cabin; others battered to death on rocks; 8 buried in Quarantine Station cemetery. Captain exonerated by Steam Navigation Board, praised for attempts to save vessel and those onboard. Cheviot bought for inter-colonial passenger and coal-carrying trade in 1876. Had recently been re-classed A1 by Lloyd's after boilers strengthened, engines overhauled and new propeller fitted. Had earlier been in trouble with breakdowns and accidents. Valued at 20-25,000 pounds, insured for 10,000 pounds. The number of passengers and crew differs in the various reports.