# Victorian Heritage Database Report

Report generated on - 28/07/24

# **DAVID**

## Location

Point Lonsdale, Port Phillip Heads

# Victorian Heritage Register (VHR) Number

S167

#### **Date lost**

15 Apr 1850

## Official number

None

## **Construction material**

Wood

#### Hull

Wood

# **Propulsion**

Sail

## **Number of masts**

2

# Length/Breadth/Depth

76.00 Feet / 17.30 Feet / 7.00 Feet

#### **Builder**

John Eason

## Year of construction

R	mil	lŧ.	ро	rí
D	uı	ľ	NU	יוי

Northwest Bay, Tasmania

## **Built country**

Australia

# **Registration Number**

9 of 1843

## **Registration Port**

Hobart

#### **Date lost**

15 Apr 1850

# **Departure**

Hobart

#### **Destination**

Geelong

## Cargo

Timber - sawn and broad palings (UID 71, 72)<br/>
br /> Former cargo: "9000 feet timber, 200 posts and rails, 350 staves, 4000 paling" (Port Phillip Herald; 1 June 1848, 2, c1)

#### **Owner**

Charles McShane of Hobart

#### **Master**

Captain Hills

#### Weather conditions

Wind: SW force 4; clear night. Flood tide

#### **Cause of loss**

Struck Lonsdale reef due to Captain's chart differing two points from the chart in possession of the pilot (UID 71)

#### **Passenger comments**

1 cabin passenger, Mr O'Neal, and 3 steerage (UID 71)

# Statement of significance

Historically significant as an example of an early well-known timber trader

# **VHR** history

The David was travelling from Hobart with her usual cargo of timber, and having on board one cabin passenger and three steerage passengers. The run was "tedious in consequence of baffling and contrary winds." (ID 71). Just before vessel struck, mate remarked they were too close to Point Lonsdale, attempted to turn but vessel struck nevertheless. Apparently master's chart differed by 2 points from the chart currently in use. Attempt to force vessel over reef by press of canvas failed. It was believed that only the vessel was insured. David was a regular trader between Geelong and Hobart.