

Victorian Heritage Database Report

Report generated on - 19/07/24

DOROTHY

Location

Lake Colac

Victorian Heritage Register (VHR) Number

S177

Date lost

1914

Official number

101740

Propulsion

Steam - Screw

Engine specification

1 High Pressure Condensing.1 Iron and steel boiler, loaded pressure 80lbs.

Engine builder

Possibly Halliday Brothers of Sydney

Length/Breadth/Depth

55.00 Feet / 14.10 Feet / 6.20 Feet

Builder

John W. Sandry of Port Melbourne

Built port

Lake Tyers, Vic

Built country

Australia

Registration Number

5 of 1903

Date lost

1914

Owner

10 Feb 1903
John Widdis of Cunningham, sawmiller 32 shares.
Charles Arthur Widdid of Heyfield, grazier 32 shares
11 Aug 1904
Albert John Ellerker, shipping agent of Melbourne
32 shares
J. Widdis and C.Widdis 16 s

Cause of loss

Stranded and later burnt