Victorian Heritage Database Report

Report generated on - 01/05/24

EDWARD

Location

Off Ricketts Point, Port Phillip Bay

Victorian Heritage Register (VHR) Number

S200

Date lost

12 Jan 1881

Official number

None

Construction material

Wood

Hull

Wood

Propulsion

Sail

Length/Breadth/Depth

0.00 / 0.00 / 0.00

Date lost

12 Jan 1881

Departure

Dromana

Destination



Firewood

Owner

Sullivan of Sandridge

Master

Captain Charles Gray

Weather conditions

Gusty easterly or SE wind; high sea; morning (UID9, 152)

Cause of loss

Sprang a leak at 2 AM, quickly filled with water, and then capsized (UID 152)

Passenger comments

Daniel Gray, 10 years old, son of Captain, asleep in the cabin at the time (UID 9, 152)

Number of crew

1

Crew comments

John Northey

VHR history

The cutter Edward, a wooden vessel, sprang leak at 2 am, filled quickly. Captain John Gray went to cabin as vessel began to sink to rescue his 10 year-old son, Daniel, who was on trip for a pleasure ride. Twice grabbed hold of boy but washed from his grasp and drowned. Unable to locate crewman, John Northey of Sandridge, who also drowned, leaving a wife and six children in straitened circumstances. It was Northey's only trip on vessel. Gray swam for ketch's dinghy among floating wreckage. Only course possible for dinghy was before the easterly wind across Bay. After baling with his boots, he finally beached near Little River and then to Werribee where he received help from local policeman. (ID 9, 152)