

# Victorian Heritage Database Report

Report generated on - 13/10/24

---

## LADY MARY PELHAM



S405 LadyMaryPalham  
PortFairy WoodDetail



S405 LadyMaryPalham  
PortFairy EndView



S405 LadyMaryPalham  
PortFairy SideDetail



S405 LadyMaryPalham  
PortFairy SideView

---

### Location

Port Fairy

### Victorian Heritage Register (VHR) Number

S405

### Date lost

31/08/1849

### Official number

None

### Hull

Felt sheathed and coppered 1836 rig-sources. Some sources state barque<br /> pre 1844 became 2 masted brig after 1844 repaired in Launceston 1844<br /> 581.0 pre 1844 381.16 post 1844

**Number of masts**

2

**Length/Breadth/Depth**

81.00 Feet / 22.00 Feet / 14.20 Feet

**Year of construction**

1816

**Built port**

Rotherhithe

**Built country**

England

**Registration Port**

Portland

**Date lost**

31/08/1849

**Departure**

Port Fairy

**Destination**

Sydney

**Cargo**

Wheat, wool and tallow

**Owner**

S.G. Henty

**Master**

Captain Wing

**Weather conditions**

SSE force 10

**Cause of loss**

Blown ashore after taking on cargo for Sydney

## **VHR history**

The Lady Mary Pelham owned by Stephen Henty was about to ail for Sydney on the morning of 31 August when a gale sent her drifting shorewards. The captain set all sail and ran her as high as possible up the beach just level with Manifold St and all hands were saved, but she was pounded to pieces before the gale abated.