Victorian Heritage Database Report

Report generated on - 11/10/24

TEMPLAR

Location

Bass Strait, off Cape Schanck/ Cape Patterson

Victorian Heritage Register (VHR) Number

S665

Date lost

02/01/1892

Official number

79512

Construction material

Wood

Hull

Single decked, 2 masted schooner, square stern, carvel built,no galleries, no figurehead, wooden framed

Propulsion

Sail

Number of masts

2

Length/Breadth/Depth

57.70 Feet / 16.30 Feet / 5.40 Feet

Builder

James Carson

Year of construction

1879
Built port
Sandridge
Built country
Australia
Registration Number
21 of 1879
Registration Port
Melbourne
Date lost
02/01/1892
Departure
Anderson Inlet
Destination
Melbourne
Owner
1879, Sept: James Carson, Shipwright, Sandridge 64/64; 1881 The colonial Permanent Building and Investment Society; May 1884 Master Mariners of Melbourne; 1887 The Snowy River Shipping Company Ltd.; Peter Pidoto, ship owner of Melbourne
Weather conditions
Severe Gale
Cause of loss
Supposedly went ashore and wrecked during severe storm

Number of crew

3

Crew comments

Including Captain

VHR history

After leaving Andersons Inlet bound for Melbourne, the schooner Templar went missing. A search later found the wreck of the vessel off Cape Schanck. The crew of three lost their lives.