# **Victorian Heritage Database Report**

Report generated on - 13/10/24

# **WINCHESTER**

### Location

Port Phillip Bay, off Queenscliff

# Victorian Heritage Register (VHR) Number

S728

### **Date lost**

16/04/1853

# **Construction material**

Wood

### Hull

Pitch Pine topsides, sheathed with felt and yellow metal 1838, yellow metalled in 1845, 1849. Some repairs 1843.

# **Propulsion**

Sail

# **Number of masts**

3

# Length/Breadth/Depth

0.00 Feet / 0.00 Feet / 0.00 Feet

### Year of construction

1837

# **Built port**

Sunderland

# **Built country**

Е	ng	laı	nd

# **Registration Port**

Bristol

#### **Date lost**

16/04/1853

### **Departure**

Melbourne

#### **Destination**

Newcastle

### Cargo

50 pounds of gunpowder on board

#### **Owner**

Bristol owned

#### Master

Captain Curry

#### Weather conditions

SE force 2. Clear

#### Cause of loss

Burnt at sea

# **VHR** history

Was at anchor as a strong wouth-westerly breeze prevented proceeding to sea, head pointing north-east. At about 11 am fire broke out in lazarette (aft of vessel). The crew immediately took to the boats, refusing to assist in putting out fire. The Mate apparently prevented crew from leaving without captain. The 50 lbs gunpowder on board exploded after about 2 hours; half an hour later the vessel was burnt to within a few feet of its waterline. Lying between the two Pope's Eye buoys, the lighthouse bearing N by W. According to captain, fire resulted from disobeying orders and carelessness when a crew member went below with a naked light. Either the captain did not issue the appropriate orders or the men would not obey him and the fire was not extinguished. Crew of 16 on 1853 voyage Bristol-Melbourne. The Winchester was burnt to its waterline while lying at anchor off Queenscliff. The crew did not want to assist the captain in extinguishing the fire.