"AMF Officers" Shed



"AMF Officers" Shed

Location

89-91 Lerderderg Street. BACCHUS MARSH, MOORABOOL SHIRE

Municipality

MOORABOOL SHIRE

Level of significance

Included in Heritage Overlay

Heritage Overlay Numbers

HO96

Heritage Listing

Moorabool Shire

Statement of Significance

Last updated on - July 10, 2015

What is significant?

The former Military Hut at 89 Lerderderg Street, Bacchus Marsh.

How is it significant?

The former Military Hut at 89 Lerderderg Street, Bacchus Marsh is of local historical and aesthetic significance to the Shire of Moorabool.

Why is it significant?

The former Military Hut at 89 Lerderderg Street, Bacchus Marsh is of historical significance for its associations with, and as a remnant building from, the former Military Camp at Darley. This building has local significance in demonstrating the effect of government action and international engagement in the Second World War.

The former Military Hut at 89 Lerderderg Street, Bacchus Marsh is of aesthetic significance as a particularly intact World War Two iron clad military hut, possibly an officers' mess from the Darley Military Camp, erected in 1940 and relocated in 1945. Key original features of the building include the overall form and scale, corrugated metal sheet cladding, front double timber doors, and evenly spaced timber framed awning windows to the side elevations.

Heritage
Study/ConsultantMoorabool - Bacchus Marsh Heritage Study 1995, Richard Peterson and Daniel
Catrice, 1995;Hermes Number124288Property Number

Physical Description 1

Corrugated iron, gable roofed shed, erected with the gable facing the road. The roof appears to be clad in asbestos cement. It bears a painted timber sign on one door: "AMF Officers". There are (now) vehicular timber doors in the gableend, and five four-paned small windows and two doors in the right hand side. The cladding is fixed horizontally. There are two small "Sunshine" vehicular metal gates and an old flat top picket fence (unpainted) with rails and split posts.

Intactness

Excellent.

Historical Australian Themes

Governing

Usage/Former Usage

USE: Store??

PREVIOUS USE: Military officers' mess"?

Physical Conditions

CONDITIONS & THREATS: Fair. Roofplumbing needs repair. Downpipes do not appear to be longer than 300mm and so discharge down the walls. Spouting is damaged and corroding.

This place/object may be included in the Victorian Heritage Register pursuant to the Heritage Act 2017. Check the Victorian Heritage Database, selecting 'Heritage Victoria' as the place source.

For further details about Heritage Overlay places, contact the relevant local council or go to Planning Schemes Online http://planningschemes.dpcd.vic.gov.au/