

---

## Former Kinglake RSL Hall



RSL Hall (Former)



RSL Hall (Former) II

---

### Location

96 Whittlesea - Kinglake Road KINGLAKE, Murrindindi Shire

### Municipality

MURRINDINDI SHIRE

### Level of significance

-

### Heritage Listing

Vic. War Heritage Inventory

---

Heritage Study/Consultant	Murrindindi - Murrindindi Heritage Study Stage One, Context Pty Ltd, 2006;
Construction dates	1952,
Other Names	Kinglake Gallery,
Hermes Number	125630
Property Number	

---

## **Physical Description 1**

The former RSL Hall is a single storey building with a cream brick facade and fibro cladding for the side and rear walls. The lower portion of these elevations are clad in weatherboards and the hall has a gabled corrugated galvanised iron roof. The windows and door hoods are new with the door hoods featuring lattice work.

## **Integrity**

Minor Modifications

## **Physical Conditions**

Good

## **Physical Description 2**

Location- On front corner of Kinglake Trust Reserve, next to SES.

## **Physical Description 3**

Key element - Building

## **Usage/Former Usage**

Community

## **Physical Description 4**

Key Features/Materials  
HALLstyle - Utalitarian  
WALLS - Other  
ROOF - Corrugated iron

## **Veterans Description for Public**

The former RSL Hall, at 96 Whittlesea - Kinglake Road, was built in 1952. It is a single storey building with a cream brick facade and fibro cladding for the side and rear walls. The lower portion of these elevations is clad in weatherboards and the hall has a gabled corrugated galvanised iron roof. The windows and door hoods are new with the door hoods featuring lattice work.

*This place/object may be included in the Victorian Heritage Register pursuant to the Heritage Act 2017. Check the Victorian Heritage Database, selecting 'Heritage Victoria' as the place source.*

*For further details about Heritage Overlay places, contact the relevant local council or go to Planning Schemes Online <http://planningschemes.dpcd.vic.gov.au/>*