
Former Kinglake RSL Hall



RSL Hall (Former)



RSL Hall (Former) II

Location

96 Whittlesea - Kinglake Road KINGLAKE, Murrindindi Shire

Municipality

MURRINDINDI SHIRE

Level of significance

-

Heritage Listing

Vic. War Heritage Inventory

Heritage Study/Consultant	Murrindindi - Murrindindi Heritage Study Stage One, Context Pty Ltd, 2006;
Construction dates	1952,
Other Names	Kinglake Gallery,
Hermes Number	125630
Property Number	

Physical Description 1

The former RSL Hall is a single storey building with a cream brick facade and fibro cladding for the side and rear walls. The lower portion of these elevations are clad in weatherboards and the hall has a gabled corrugated galvanised iron roof. The windows and door hoods are new with the door hoods featuring lattice work.

Integrity

Minor Modifications

Physical Conditions

Good

Physical Description 2

Location- On front corner of Kinglake Trust Reserve, next to SES.

Physical Description 3

Key element - Building

Usage/Former Usage

Community

Physical Description 4

Key Features/Materials
HALLstyle - Utalitarian
WALLS - Other
ROOF - Corrugated iron

Veterans Description for Public

The former RSL Hall, at 96 Whittlesea - Kinglake Road, was built in 1952. It is a single storey building with a cream brick facade and fibro cladding for the side and rear walls. The lower portion of these elevations is clad in weatherboards and the hall has a gabled corrugated galvanised iron roof. The windows and door hoods are new with the door hoods featuring lattice work.

This place/object may be included in the Victorian Heritage Register pursuant to the Heritage Act 2017. Check the Victorian Heritage Database, selecting 'Heritage Victoria' as the place source.

For further details about Heritage Overlay places, contact the relevant local council or go to Planning Schemes Online <http://planningschemes.dpcd.vic.gov.au/>