Victorian Heritage Database Report

House at 80 Victoria Street



House at 80 Victoria Street WILLIAMSTOWN, Hobsons Bay Heritage Study 2006



House at 80 Victoria Street WILLIAMSTOWN, Hobsons Bay Heritage Study 2006

Location

80 Victoria Street WILLIAMSTOWN, Hobsons Bay City

Municipality

HOBSONS BAY CITY

Level of significance

Incl in HO area contributory

Heritage Overlay Numbers

HO312

Heritage Listing

Hobsons Bay City

Statement of Significance

Last updated on -

What is Significant?

The house, constructed by Peter Rodger in 1913, at 80 Victoria Street, Williamstown.

How is it Significant?

The house at 80 Victoria Street, Williamstown is of local historic and aesthetic significance to the City of Hobsons Bay.

Why is it Significant?

Historically, it was closely associated with the locally important Rodger family who constructed other unusual and successfully designed houses in Williamstown and large contracts within Victoria. (AHC criterion H1)

Aesthetically, it is an unusual, original and skilful combination of forms outside of the prevailing Queen Anne styles but combining some of its elements with late Victorian traits also possesses valuable period details. (AHC criteria E1 and F1)

Heritage Study/Consultant Hobsons Bay - Hobsons Bay Heritage Study, Hobsons Bay City Council, 2006;

Hermes Number 22293

Property Number

Physical Description 1

An asymmetrically composed, two storey, face brick house with a hipped and slated main roof set beside a trussgabled, two storey, stuccoed bay on the south side. Between this and a one storey, five-sided window bay at the front elevation, a two level return timber verandah, extends beyond the front face of the house in a three sided bayed form. Iron balustrading is combined with a pressed sheet iron skirt, acting as a frieze to the ground level of the verandah.

The house is generally original except for stuccoing of the bay on the south, and the replacement of the original unusual sculptured profile square-top picket fence, gate and portal (as identified and documented by the 1993 Study) by an unrelated Victorian-era picket fence.

Integrity

External Integrity

Integrity - High. Condition - Good.

Physical Description 2

Context

A dominant (scale, corner site) and contributory element to the Victoria Street precinct, which also relates to timber detailing on 78 and 96 Victoria Street.

Historical Australian Themes

Making Suburbs

Physical Description 3

Associations

Peter Rodger

This place/object may be included in the Victorian Heritage Register pursuant to the Heritage Act 2017. Check the Victorian Heritage Database, selecting 'Heritage Victoria' as the place source.

For further details about Heritage Overlay places, contact the relevant local council or go to Planning Schemes Online <u>http://planningschemes.dpcd.vic.gov.au/</u>