
CHRIST CHURCH OF ENGLAND (FORMER)



22578 Former Christ Church
of England - 177 Foote
Street, Templestowe

Location

177 Foote Street TEMPLESTOWE, Manningham City

Municipality

MANNINGHAM CITY

Level of significance

Recommended for Heritage Overlay

Heritage Listing

Manningham City

Statement of Significance

Last updated on -

What is Significant?

Christ Church of England (former), constructed 1900, at 177 Foote Street, Templestowe.

How is it Significant?

Christ Church of England (former), 177 Foote Street, Templestowe, is of local historic and social significance to Manningham City.

Why is it Significant?

Christ Church of England (former) has historic significance as one of just two nineteenth-century churches that provide evidence of the initial settlement and development of the Templestowe community during the late nineteenth century. It is one of just seven surviving nineteenth-century buildings in the Templestowe district. (RNE criteria A.4, B.2, & D.2)

Christ Church of England (former) has social significance as it has played an important role in the development of the Templestowe community over a one hundred year period. Although no longer used as a church, the present arts centre use continues its role as a community building. (RNE criterion G.1)

Heritage Study/Consultant Manningham - Manningham Heritage Study Review, Context Pty Ltd, 2006;

Other Names Manningham Arts Centre,

Hermes Number 22578

Property Number

Historical Australian Themes

Local Themes

6.02 - Churches

Physical Description 1

The former Christ Church of England, constructed c.1900, is a simple Victorian Carpenter Gothic church with pointed leadlight windows and a porch. The upper gable is decorated with timber rails. Although there have been minor modifications and additions at the rear, the building is in good condition. It compares with the former Templestowe Presbyterian Church at 104 Atkinson Street, Templestowe (refer to separate citation in this Study).

There are other more recent buildings and a large car park at the rear with access from Foote Street. These are unrelated to the early development of the church and are not significant.

Physical Conditions

Condition Good

Integrity

Integrity Minor modifications

Physical Description 2

Threats None apparent

Physical Description 3

Key elements

Building

This place/object may be included in the Victorian Heritage Register pursuant to the Heritage Act 2017. Check the Victorian Heritage Database, selecting 'Heritage Victoria' as the place source.

For further details about Heritage Overlay places, contact the relevant local council or go to Planning Schemes Online <http://planningschemes.dpcd.vic.gov.au/>